

Livingston

Evaluation of the **Mission Field** yielded the following PCI values.

Section	Critical PCI	Surveyed PCIs				Predicted PCIs	
		1988	1991	1994	1997	2002	2007
A-1	60	XX	XX	93	86	70	64
A-2	55	XX	XX	96	92	74	55
R-1	60	XX	XX	99	92	76	67
R-2	55	XX	XX	99	90	75	64
T-1	60	XX	XX	100	87	73	66
T-2	55	XX	XX	98	77	67	58
T-3	55	XX	XX	99	100	79	66
T-4	50	XX	XX	95	86	75	65

Pavement Condition Index (PCI) to **Pavement Condition Rating** conversion:

0 ≤ **Failed** ≤ 10 < **Very Poor** ≤ 25 < **Poor** ≤ 40 < **Fair** ≤ 55 < **Good** ≤ 70 < **Very Good** ≤ 85 < **Excellent** ≤ 100

"XX" in PCI columns indicates previous PCI values have been voided to account for new construction.

No entry in PCI columns indicates no inspection of the pavement section for the year.

PCI predictions are based on the assumption that current maintenance practices will continue with no major reconstruction.

All of your pavements are currently rated at "very good" or above. They are projected to remain above their critical PCIs for at least 10 years with continued routine maintenance.